
INSTALLATION DIAGRAM


PARTS LIST




Screws

A1	M6x12	4 PCS
B1	M6x20	2 PCS
C1		1 PCS
D1		1 PCS


ALLEN WRENCH



STEP 1



STEP 2



STEP3

